

SAMPLE MATERIAL WORK SHEET

Source: S. K. D. mba

Part Number: 6263892

Part Name: Arm-5" Steerin Knuckle 4/c

B/P Date: 7/17/73

Inspected by: Kenneth Hammons

Date 5/21/84

[illegible]

CHEVROLET-DETROIT GEAR & AXLE
DIVISION OF GENERAL MOTORS CORPORATION
1840 HOLBROOK AVENUE
DETROIT MICHIGAN 48212

#3 Rlt#6

INSPECTION SAMPLE APPROVAL REPORT

Model _____
Year _____

Date of Issuance: 8-7-84
Checked to B/P Dated: 7-17-73
Samples from Lot Number: Sample
Date Received: 7-18-84
Supplier: K. S. D. Mfg.

Part Number: 6263891
Part Name: Arm-Steering Knuckle L/C/A
Quantity: 1 pc.
Pattern(s) Number: _____

INSPECTION RESULTS

Dimensional Conformance Check: ☐ Dimensionally OK ☒ See attached sheet(s)

Chevrolet Laboratories

Lab Lot Number: 1008 - 1099

Laboratory

Analysis: ☐ Accept ☐ Reject ☐ Passable

Comments: _____

Lamut Inspector: Kenneth Harmons Date: 8-7-84

DISPOSITION

Based on the results above, your samples have been:

- ☒ Approved Item #4 to be corrected by source per J. Zelle at S.K.D. on 8-8-84.
(Corrected sample to be submitted)
Not in Area Under Suspicion
- ☐ Provisionally approved
- ☐ Correct and proceed with shipments; corrections must be made on the first production shipment.
- ☐ Proceed with _____ pieces in production shipments and submit new samples.
- ☐ Accept as received. Proceed with shipments; however, samples for new dies or molds must reflect corrections to dimensional discrepancies.
- ☐ REJECT - SUBMIT NEW SAMPLES.

Supplier verbally contacted: Jerry Zelle by: Kenneth Harmons Date: 8-8-84

Comments: _____

Disposition authorized by: George De Ville Date: 8-6-84

Superintendent of Inspection

Date: _____

000152

INSPECTION SAMPLE APPROVAL REPORT

1 of 1

=

of Date: 8/7/84 Part Number: 6263891
 of Date: 7/17/73 Part Name: Asm - Steering Knuckle. L/C/A
 of Number: Sample of: L/C
 of Date: 7/18/84 of Number:
 of: S.K.D. mfg

Inspection	Conformant	Results	Dimensionally OK	Line at back sheet

of Date: 1008-1010 of: Accept of: able

ments: ILLEGIBLE

of Date: Kenneth Horne 8/7/84

DISPOSITION

of Date: the results of: our samples have been:

of Date: NOTES Item #4 to be corrected by source,
Ben. G. Zell at S.K.D. 8/8/84 (sample to be submitted)

of Date: ionally app
 of Date: Correct of: proceed with shipments: corrections in of: in the in
 of Date: Proceed of: pieces in produr of: and the
 of Date: now sample
 of Date: at receiver of: proceed with shipment: however, sample of: ies or this
 of Date: refers correct of: to dimension: discrepancies.

of Date: REJECT of: SUBMIT NEW of: PLES.

of Date: inlier verbally contr of: by: Kenneth Horne of: Date: 8-8-4

of Date: ments: of: _____ of: _____

of Date: thru of: 8-8-4 of: 000158

of Date: per inter of: ion

SAMPLE MATERIAL WORK SHEET

Serial	S.K.D. m/p	Part Number	6263891
Part	Arm - Steering Knuckle 4/61A	S.P. Date	7/17/73
Inspected by:	Kenneth Thompson	Date	8/6/84

[illegible]

JUL 05 1984

2

Truck & Bus Group



Truck & Bus Group
General Motors Corporation
31 Jackson Street
Pontiac, Michigan 48058

cc
T. CASEY
D. FORNIEFER
R. TURKETT
FYI
Ply

June 27, 1984


Mr. A. M. Brown Jr.
Detroit Gear and Axle
1840 Holbrook Avenue
Detroit, MI 48212

Subject: Validation Testing Update

Lower control arms 6263891-2 are approved for use in arm asms 14005167-8.

You will be updated regarding the balance of the test program as significant portions are completed.

Very truly yours,


D. C. Raber
Truck Chassis Components

DCR/kaj

cc: M. B. Madden
R. Stach
H. L. Western
R. D. Wood



000155



Saginaw

Inter-Organizational

Subject: Test Information Report
T-876-03P-002LT

Date: 3-31-87

From: Mr. D. H. Pokriefka

To: Mr. E. L. Sturm

GM Truck Group
Milford Proving Ground
Vehicle # 2GCHG31K6H410005
Mileage: 8755

L.H. Lower Control Arm
Part # 14066885

Cross Shaft Bushing Torque:

240 Ft. Lbs.
210 Ft. Lbs.
B/P Spec 125 Min.

Shaft Movement:

Free

Jounce Bumper:

Missing

Shock Brkt & Reinforcement Welds:

OK

Jounce Bumper Brkt Welds

See attached Lab Report
6-44 and 6-43

Ball Stud:

Push out load "0"
B/P Spec 2000 # Min.

Lower Control Arm Stamping:

50 MM crack at rear of ball stud

Summary: See Lab Reports 6-43 & 6-44

The lower control arm stamping from SKD appears to have a small radius at the side wall to the ball stud nose. SKD has changed the trim to increase the radius to one inch and provide additional strength in the ball stud area.

The front suspension may be loaded at maximum or beyond maximum load range which is evidenced by broken welds and compressed jounce bumpers.

D. H. Pokriefka
D. H. Pokriefka
Chief Inspector
T-876

cc: R. M. Brown

000156

Truck & Bus Operations
Reliability Department
Materials Laboratories

Truck & Bus Group



TECHNICAL REPORT

TO: J. M. Quinn
FROM: G. L. Haviland
SUBJECT: Field Complaint; P-Truck Lower
Control Arm, P/N 15594133
REFERENCE: IR 07330, 9/30/87

DATE: 12/4/87
REPORT NO: 17-62
COPIES: P.F.Birsa —
R.E.Rinebolt


Foreword:

One lower control arm broken at its ball stud hole was submitted by Product Service for examination.

Operator: American Bakeries
VIN: 1CDEP32J6F3508398
Mileage: 56,746

Summary:

The control arm was sent to the vendor, Saginaw Division, for their examination. Their report is attached.


G. L. Haviland
Reliability Metallurgist
Special Analysis Group
6-3438
Reliability Laboratories

/ncd

d 6- 11 18.

ICE PROB

f09462hg

000157



Saginaw

Inter-Organizational

Subject: 15594133 Lower Control Arm

Date: 11-30-87

From: Mr. D. H. Pokriefka

To: Mr. G. L. Haviland

American Bakeries

Vehicle # 16DHP32J6F3508398

Mileage: 56,746

3/4 Ton L.H. Lower Control Arm

Cross Shaft Bushing torque	220 ft. lbs.
	210 ft. lbs.
	Spec. 125 ft. lbs. min.

Shaft movement:	Free
Jounce bumper:	OK
Brackets:	Shock bracket OK
	Jounce bracket OK
Bushings:	Seated
Ball Stud:	Pulled out of L.C.A.

Tear Down Inspection: Arm stamping cracked from the outer wall end face to the ball stud mounting hole. Stamping source is SKD

Summary: The lower control arm stamping from the SKD Company appears to have a small radius at the transition of the side wall to the ball stud nose. The crack appears to have started at the base of the radius. The stamping was changed on 7-18-86 to incorporate a one inch radius to provide additional strength in the ball stud area.

D. H. Pokriefka

D. H. Pokriefka
Chief Inspector. Plant # 56

000158



Saginaw

QAT 231 141

Subject 15594133 Lower Control Arm

Date 1-19-88

From Mr. D. H. Pokriefka

To Mr. G. L. Haviland

Harrison Delivery

Vehicle # 1GDHP32M3G3502666

Mileage 46,000

3/4 Ton L.H. Lower Control Arm

Cross Shaft Bushing Torque

200 Ft. lbs
195 Ft. lbs
Spec. 125 Ft. lbs Min.

Shaft Movement

Free

Jounce Bumper

Missing

Brackets

Shock OK
Jounce OK

Bushings

Seated

Ball Stud

Missing pulled out of L.C.A.

Tear Down Inspection Arm stamping is cracked from the outer wall end face to the ball stud mounting hole. The bottom surface of the arm is scrubbed off and the origin of the crack is not evident.

Summary The lower control arm stamping is from the SKD Company and does not have a julian date stamp. The crack is similar in appearance to the known stamping dates and probably started in the radius at the transition of the side wall to the ball stud nose. The stamping configuration was changed on 7-18-86 to incorporate a one inch radius to provide additional strength in the ball stud area.

D. N. Pokriefka

D. H. Pokriefka
Chief Inspector. Plant # 56

000159

8-7-87

11

G-30 L/C/A HISTORY
(P/N 14026585 L/C/A ASM AS SERVICED)

Ø7AUG87 8:25 EARL GAUTSCHE - FLEET SERVICE CAP 8-562-5533

- G-30 CUTAWAYS (18 ASST) SCHOOL BUSES, 6.2 L DIESELS
- * • 13 L/C/A ASM CRACKED IN BALL JOINT AREA (LH) ONLY
(P/N 14026585 SERVICED ASM)
- * • 45 BUSES IN FLEET (TYPICAL VIN # 29BHG31J194101766)
- OCCURANCES AT APPROX 50,000 + MILES
- BUSES MADE BY CARPENTER (BODY WORKS)
- (SAN DIEGO CITY SCHOOLS
MAINTENANCE DEPT
2351 CARDINAL LANE
SAN DIEGO, CALIF 92123
ATTN: DAN HARGRAVES (MAINT. MGR.) (619) 278-7440)
- PHOTOS PROVIDED (POOR)
- STATE HIGHWAY PATROL AND D.O.T. INVOLVED

Ø7AUG87 2:26 DAN HARGRAVES - (MAINT MGR,

- FRT SUSP TAGS ON '2, VEHICLES VERIFIED AS:
SAP 15597838
- * • 9 L/C/A ASM CRACKED CHANGED 9 (DIFFERS FROM E. GAUTSCHE)
- HELWIG TRANSVERSE LEAF SPRING ADDED (BY HIMSELF)
DUE TO TIRES WEARING OUT AT 8000 MILES (RADIAL TIRES)
- 16L6R PARTS WEARING OUT AT 3-4000 MILES
- * • 33 BUSES IN FLEET (DIFFERS FROM E. GAUTSCHE)
- TOLD BY THOMAS BUS COMPANY/COMPETITOR TO CARPENTER THAT
THE CHASSIS USED IS ONLY 8600 GVW.
- CARPENTER MAINTAINS THAT VEHICLE IS RATED AT 10,000 GVW.

1ØAUG87 8:05 GENE STURM - TVB CHASSIS DESIGN 616R-3-292-3103

- MUST SEND IDENTICAL REPLACEMENT L/C/A ASM. (NOT THOSE
REINFORCED FOR F-92 HEAVY DUTY OPTION)
- NO EVIDENCE TO SUPPORT A NEED FOR HEAVY DUTY PARTS 000160
OR CROSS MEMBER PARTS MADE TO PRINT MEET ALL
SCHEDULE REQUIREMENTS.
- THIS PROBLEM IS DUE TO IMPROPER TRANSITION RADIUS AT THE
U. - (A.G. T.R. # T-879-03A-002LT)

11 A


16AUG87 11:30 EARL GAUTSCHE

- SHIP (13) PC LH 19026585
(3) ~~PC~~ PC RH 19026586 (FIGURE RAISED 12AUG87)
- WILL BE ORDERED THRU WAREHOUSING WITH A P.O.
(AGREED TO DO THIS PER SD REQUEST, ORIGINAL
DIRECTION FROM AUG 87AUG87)

12AUG87 8:11 EARL GAUTSCHE

- KNOWN AREAS WITH COMPLAINTS -
 - SAN DIEGO SCHOOL DISTRICT (DESCRIBED)
 - GALIN TRANSPORTATION CO., STARHOPE N.J.
75 VEH. IN FLEET, 2 LGA ASK CANCELED THIS MORN.
6.2L DIESEL, 6-30;
VIN # 2G8GG35J7F919015
2G8GG35J3F9139519
(VIN HISTORIES CLEAN)
DAVE BRUKER, CALL YESTERDAY.
- 'UNKNOWN SOURCE' NORTH DAKOTA
LH 6-30 CANCELED
OTHER INFO NOT IMMEDIATELY AVAILABLE

000161



1624531115 2101766



San Diego Federal District #1
 L. Susan R. Smith
 2547 S. W. 6th 101766
 50165 N.W. Pub #14026-755?

0000



133 16 #2
 #2 San Diego #1
 Charleston Record 67792

ILLEGIBLE

000162

STS

STRUCTURAL TESTING SERVICES INC.

5839 EXECUTIVE DRIVE EAST WESTLAND, MICHIGAN 48185
313 326 7090

January 25, 1984

Mr. Ron Stach
Chevrolet Gear and Axle
1840 Holbrook
Detroit, Michigan 48212

Dear Mr. Stach:

Subject: Truck Crossmember and Suspension Component Testing

Based on our understanding of your requirements, we are enclosing cost and timing to conduct the required test program. Timing is based on a 3-shift, 6-day per week effort.

Costs:

<u>Test</u>	2 Shifts,	3 Shifts,
	<u>5 1/2 Days per Week</u>	<u>6 Days per Week</u>
Brake Reaction (0282)	\$1,200 each sample	\$2,700 each sample
2g/2g (0158)	\$3,400 each sample	\$4,900 each sample
Setup of second test site dedicated to 2g/2g testing (One-time charge).		\$4,000
Conversion of first test site from brake reaction to 2g/2g (One-time charge) as quoted.		\$2,500

Timing: (see enclosure)

If you have any questions, please contact me.

Thank you for this opportunity to quote your testing needs.

Sincerely,

M.B. Madden
M. B. Madden, Manager
Marketing & Sales Engineering

MBM:cd
Enclosure

*not received
\$14 P. 1-27-84*

000163

Mr. Ron Stach
Chevrolet Gear and Axle

January 25, 1984
Page 2

Time Schedule
Truck Crossmember and Suspension Component Testing

Estimated completion of 3 samples each model (based on 3-shift, 6-day per week operation).

Crossmember Assemblies
Proj. 732-733

Test	911	640	158	138
Brake Reaction (0282) First Setup	Compl.	Compl.	2/2	2/11
2g/2g (0158) Second Setup	2/25	3/13	3/27	4/12

Test 0282 - Estimate 2.5 days per sample
Test 0158 - Estimate 4.5 days per sample

2
2
21

Suspension Arms

Test	6263851-2 UCA	6263811-2 UCA 6263891-2 LCA	337581-2 UCA 6263891-2 LCA
Brake Reaction (0282) First Setup	2/21	3/1	3/10
2g/2g (0158) Convert First Setup	2/4	4/4 5/19	2 2/13
2g/2g Second Setup	—	— 1/13	1/25 5/28

Test 0282: Estimate 2.5 days per sample
Test 0158: Estimate 13 days per sample

1 5/4 2 shifts 3 1/2 days
4/5
2 5/4 3 shifts 6 days

7
30
39
21
60

000164



STS

STRUCTURAL TESTING SERVICES INC.

5836 EXECUTIVE DRIVE EAST WESTLAND, MICHIGAN 48185
313 328 7090

January 30, 1984

Mr. Ron Stach
Chevrolet Gear and Axle
1840 Holbrook
Detroit, Michigan 48212

Dear Mr. Stach:

Subject: Truck Crossmember and Suspension Component Testing
Re-Quote (See Original Quote Dated 1/25/84)

Based on our understanding of your requirements, we are enclosing cost and timing to conduct the required test program. Timing is based on a 3-shift, 6-day per week effort.

Costs:	(As Quoted) 2 Shifts, <u>5 1/2 Days per Week</u>	3 Shifts, <u>6 Days per Week</u>
<u>Test</u>		
Brake Reaction (0282)	\$1,200 each sample	\$2,700 each sample
All		
2g/2g (0158)	\$3,400 each sample	\$4,900 each sample
Crossmember Assys.		
2g/2g (0158)	---	\$14,200 each sample
Suspension Components		
Setup of second test site dedicated to 2g/2g testing (One-time charge).		\$4,000
Conversion of first test site from brake reaction to 2g/2g (One-time charge), as quoted.		\$2,500

Timing: (see enclosure)

If you have any questions, please contact me.

Thank you for this opportunity to quote your testing needs.

Sincerely,

M. B. Madden

M. B. Madden, Manager
Marketing & Sales Engineering

84 FEB 3 3 32

MBM:cd

Enclosure

CHEVROLET GEAR & AXLE
DETROIT, MICHIGAN 48212
PL. CHASSIS DEPT.

000165

Mr. Ron Stach
Chevrolet Gear and Axle

Feb 20, 1984
January 30, 1984
Page 2

Time Schedule *
Truck Crossmember and Suspension Component Testing

Estimated completion of 3 samples each model (based on 3-shift, 6-day per week operation).

Crossmember Assemblies

Proj. 732-733

Test	911	640	158	138
Brake Reaction (0282)	Compl.	Compl.	2/2	2/11
First Setup				
2g/2g (0158)	3/1	3/17	3/3	4/19
Second Setup	2/25	3/13	3/27	4/12

Test 0282 - Estimate 2.5 days per sample

Test 0158 - Estimate 4.5 days per sample

Suspension Arms

Test	6263851-2 UCA	6263811-2 UCA 6263851-2 LCA	337581-2 UCA 6263891-2 LCA
Brake Reaction (0282)	3/1	3/23	4/3
First Setup	2/21	3/1	3/10
2g/2g (0158)	--	5/2	6/14
Convert First Setup		4/4	5/5 (2 sets)
2g/2g	--	---	5/19
Second Setup			4/30 (1 set)

Test 0282: Estimate 2.5 days per sample

Test 0158: Estimate 13 days per sample

- * Based on support parts and information being available as needed.

000166

STG

CHEVROLET GEAR & AXLE
DIVISION, DETROIT DEPT.

84 FEB 28 P 3:29

STRUCTURAL TESTING SERVICES INC.

5600 EXECUTIVE DRIVE EAST WESTLAND, MICHIGAN 48186
313 326 7090

February 20, 1984

Mr. R. Stach
Purchasing Department
Chevrolet Gear and Axle Division
General Motors Corporation
1840 Holbrook
Detroit, Michigan 48212

Dear Mr. Stach:

Subject: Korreck Crossmember Test Status
Control Arm Test Status

Enclosed is the revised time schedule, based on known information as of this date.

Five (5) days were lost on the startup of Setup #2 due to shortage of correct steering linkage assemblies. From the early results of the 2G test, it appears the test may take longer than anticipated because of numerous spring failures which generate down time.

The brake reaction test on the 14067158 assemblies required 5 samples instead of 3. The first sample was assembled with incorrect parts. The fourth sample did not make the test bogie and was terminated at 84,000 cycles.

As of this writing, both test sites are in operation.

We have started to invoice Korreck on a monthly basis for the crossmember test work. We assume they should also be charged for the 3rd-shift premium, as applied to the crossmember work, excluding the 14067138 assemblies. PLEASE ADVISE.

At the end of February, we will need to start invoicing Chevrolet Gear & Axle for the second setup and test work completed. We do not have a purchase order at this time. PLEASE ADVISE.

000167

Mr. R. Stach
Chevrolet Gear and Axle Division

February 20, 1984
Page 2

As you know, this combined crossmember/control arm test program is of substantial test magnitude. Our estimated completion dates are ambitious.

If you have any questions, please contact me.

Sincerely,

M. B. Madden

M. B. Madden, Manager
Marketing & Sales Engineering

MBM:cd

Enclosure: Time Schedule

000168

Mr. Ron Stach
Chevrolet Gear and Axle Division

February 20, 1984
Page 3

Time Schedule *
Truck Crossmember and Suspension Component Testing

Estimated completion of 3 samples each model (based on 3-shift, 6-day per week operation).

Crossmember Assemblies
Proj. 732-733

Test.	4578	672	674	1338
	911	640	158	138
Brake Reaction (0282) First Setup	Compl.	Compl.	Compl.	3/10
2g/2g (0158) Second Setup	3/1	3/17	4/3	4/19

Test 0282 - Estimate 2.5 days per sample.

Test 0158 - Estimate 4.5 days per sample.

Suspension Arms

Test	6263851-2 UCA	6263811-2 UCA 6263891-2 LCA	337581-2 UCA 6263891-2 LCA
Brake Reaction (0282) First Setup & (0283)	3/1	3/23	4/3
2g/2g (0158) Convert First Setup	---	5/30	6/14 (1 Set)
2g/2g Second Setup	---	---	5/19 (2 Sets)

Test 0282 - Estimate 2.5 days per sample.

Test 0158 - Estimate 13 days per sample.

Test 0283 - Estimate 1 day per sample.

DUNC

* Based on support parts and information being available as needed.

000169

June 18, 1984

TEST RESULTS SUMMARY

<u>Status</u>		<u>Remarks</u>
Test 795 (Test 0158) 2g/2g PN 6263891-2 (CCJ) (Held Assy. 14005167-8)	Completed Sample Sets #1, #2 to 500,000 cycles. Third set in progress. Expected completion June 29. Three Sample Sets required. Test to start July 2. Expected completion August 13.	Sample #1 found L.H. shock bracket very close to edge of arm, causing failure at 189,000 cycles. At completion of 500,000 cycles, cracks were noted in spring seat area.
Test 794 (Test 0282) Brake Reaction (Test 0283) Panic Brake PN 6263851-2 (DHS) U C/A PN 6263811-2 (CCJ) U C/A PN 337501-2 (CCB) U C/A	Three Sample Sets complete March 1, 1984. Three Sample Sets complete May 2, 1984. Two L.H. and one R.H. complete to 100,000 cycles as of June 15, 1984. NOTE: Second R.H. in progress. Third L.H. in progress.	Validation complete. Validation complete. Sample #1 R.H. failed at rear bushing reinforcement 49,300 cycles. Sample #2 R.H. failed as noted at 36,860 cycles. Sample #3 R.H. failed as noted at 38,870 cycles.
(Test 0282) Brake Reaction PN 6263891-2 (CCJ) (Held Assy. 14005167-8)	One L.H. complete to 100,000 cycles (SKD-2) Test to be conducted after U C/A's 337501-2.	Sample #1 (SKD-1) failed at 26,670 cycles forward bushing extrusion. Sample #1 (SKD-2) R.H. failed 55,350 cycles. Sample #2 (SKD-2) R.H. failed 74,650 cycles.
PN 6263891-2 (CCB) (Held Assy. 14005171-2)	Three Sample Sets completed June 15, 1984 to 100,000 cycles each.	

000170

STSSTRUCTURAL TESTING SERVICES, INC.5859 EXECUTIVE DRIVE EAST WESTLAND, MICH. 48185
(313) 326-090

October 2, 1984

Mr. Ron Stach
Purchasing Department
Chevrolet Gear and Axle Division
General Motors Corporation
1840 Holbrook
Detroit, MI 48212

SP

Dear Mr. Stach:

Subject: Completion of Upper and Lower Control Arm Validation Testing
Test Results Summary - Tests #794, #795

S.T.S. Test No.	Test Proc.	C/A No.	Sample No.	Remarks
Brake Reaction 794	0282	Upper C/A 6263851	1, 2, 3	Completed 100,000 cycles and accepted.
794	0282	Upper C/A 6263852	1, 2, 3	
794	0283	Upper C/A 6263851	4, 5, 6	Completed 30 cycles forward and 10 cycles rearward and accepted.
794	0283	Upper C/A 6263852	4, 5, 6	Completed 30 cycles forward and 10 cycles rearward and accepted.
794	0282	Upper C/A 6263811	7, 8, 9	Completed 100,000 cycles and accepted
794	0282	Upper C/A 6263812	7, 8, 9	
794	0283	Upper C/A 6263811	10, 11, 12	Completed 30 cycles forward and 10 cycles rearward and accepted.
794	0283	Upper C/A 6263812	10, 11, 12	Completed 30 cycles forward and 10 cycles rearward and accepted.

Upper and Lower Control Arm Validation Testing
Test Results Summary Tests #794, #795

S.T.S. Test No.	Test Proc.	C/A No.	Sample No.	Remarks
794	0282	Upper C/A 337581	14A	Completed 100,000 cycles and accepted.
794	0282	Upper C/A 337581	14B	
794	0282	Upper C/A 337581	15A	
794	0282	Upper C/A 337581	17A	Failed at 32,845 cycles.
794	0282	Upper C/A 337581	17B	54,994
794	0282	Upper C/A 337581	18	37,664
794	0282	Upper C/A 337581	20	Completed 100,000 cycles and accepted.
794	0282	Upper C/A 337581	21	Failed at 46,943 cycles.
794	0282	Upper C/A 337581	22	73,869
794	0282	Upper C/A 337582	14A	49,300
794	0282	Upper C/A 337582	14B	36,860
794	0282	Upper C/A 337582	14C	38,870
794	0282	Upper C/A 337582	14D	Completed 100,000 cycles and accepted.
794	0282	Upper C/A 337582	15A	Failed at 65,460 cycles.
794	0282	Upper C/A 337582	15B	57,180
794	0282	Upper C/A 337582	17A	91,065
794	0282	Upper C/A 337582	19	Completed 100,000 cycles and accepted.

Upper and Lower Control Arm Validation Testing
Test Results Summary Tests #794, #795

S.T.S. Test No.	Test Proc.	C/A No.	Sample No.	Remark:
794	0282	Lower C/A 6263891 (Assy. 1005167)	13A	Completed 100,000 cycles & accepted.
			13B	Failed at 30,000 cycles.
	0282	Lower C/A 6263892 (Assy. 1005168)	13A	55,350
			13B	74,650
794	0282	Lower C/A 6263891 (Assy. 14005171)	16	54,350
			14,15,16	Completed 100,000 cycles & accepted.
	0282	Lower C/A 6263892 (Assy. 14005172)	14,15,16	
795	0158	Lower C/A 6263891 (Assy. 1005167)	1A	Failed at 180,850 cycles.
	2g2g		1B	Completed 500,000 cycles & accepted.
			2	" "
			3	" "
795	2g2g	Lower C/A 6263892 (Assy. 1005168)	1A	Completed 680,850 cycles & accepted.
			2	500,000
			3A	Failed at 266,540 cycles.
			3B	Completed 500,000 cycles & accepted.
	0158	Lower C/A 6263891 (Assy. 14005171)	1	500,000 "
			2	"
			3	Failed at 321,090 cycles.
			4	Suspended at 36,000 cycles.


Upper and Lower Control Arm Validation Testing
Test Results Summary - Tests #794, #795

S.T.S. Test No.	Test Proc.	C/A Jo.	Sample No.	Remarks
795	0158	Lower C/A 6263892 (Assy. 14005172)	1	Failed at 165,630 cycles.
			2	264,260 cycles.
			3	Completed 570,110 cycles & accepted.
			4	Failed at 360,040 cycles.

The above test data documents the test type, cycles completed and number of samples tested. The tests were conducted under the direction of GM Truck and Bus Engineering and co-ordinated through the Gear and Axle Division. It is our understanding that approval of validation of the above listed parts has been finalized by Truck and Bus Engineering.

It has been a pleasure working with the Gear and Axle Division and Truck and Bus Engineering on this project. If you have any questions, please contact me.

Sincerely,


M. B. Madden, Manager
Marketing and Sales Engineering

MBM/mb

cc: D. Pokriefka, Gear & Axle
R. Wood, Gear & Axle
D. Raber, Truck & Bus

ATTACHMENT 'I'

000175

GM-278A

ATTACHMENT 'I'

000176



Saginaw

November 3, 1987

Mr. R. M. Hinzpeter
Truck & Bus Reliability
660 S. Blvd.
Pontiac, Michigan 48053

Subject: 1984-87 Model G,P. & R &/or C Series 30/3500 Front Lower Control Arms

Dear Mr. Hinzpeter:

Light truck front suspensions containing the subject lower control arms were supplied by Saginaw Detroit Plant # 56 and the lower control arm stampings in question were supplied by SKD Manufacturing, Division of SKD Company.

The following is a chronology of the SKD Lower Control Arms 6263891-2:

12-13-83	Project approval
5-4-84	Provisional approval dimensionally by Chevrolet-Detroit Gear & Axle. See attachment # 1 & 1A
6-27-84	Validation testing approved by Truck Chassis Engineering. See attachment # 2
7-26-84	First production shipment by SKD.
8-8-84	Approved dimensionally by Chevrolet-Detroit Gear & Axle. See attachment # 3
5-6-86	Received 2 lower control arms from Conn Limo Service and 3 lower control arms from Fink Bakery. Field Product Reports # 0235JRW & 0236JRW. All L.H. lower control arms were cracked from outer wall end face to the ball stud mounting hole. See attachments # 4, 4A, & 4B
6-?-86	Received detail layout reports from GM DeMexico showing the results of their investigation of cracked lower control arms. See attachment # 5

000177

Mid June 86 Contacted SKD to change blank and incorporate 1 inch radius at outer wall end face. L.H. Arm

7-1-86 SKD changed blank and the 1 inch radius was incorporated.

7-9-86 Saginaw letter to answer report 0325JRW & 0326JRW (correction letter attached). All Fink Bakery & Connecticut Limo Service lower control arms are SKD stampings. See attachments # 6, 6A, 6B, & 6C

7-18-86 SKD julian date (2006) finished lower control arms shipped to Saginaw with radius change. on L.H. arm.

7-21-86 Saginaw Detroit Plant # 56 systematically rotated lower control arm float. The exact date of completion is not recorded.

10-14-86 Meeting between E.L. Sturm and D. H. Pokriefka to review the lower control arms and T.I.R. # T-87G-03A-002LT. See attachment # 7 & 7A

12-?-86 Received 1 R.H. and 1 L.H. lower control arm and Fleet Service Product Report # HWD 1103. See attachment # 8

3-31-87 Letter to E.L. Sturm to answer T.I.R T-87G-03P-002LT. See attachment # 9

3-31-87 Letter to E. Albers to answer Fleet Service Product Report HWD 1103. See attachment # 10 & 10A

8-7-87 Information forwarded to D. H. Pokriefka by J.S. Michalek regarding conversation between Earl Gautsche, Fleet Service and R.M. Brown and his staff. See attachments # 11, 11A & 11B

9-15-87 Conversation with Dave Hazelhurst from Chevrolet Fleet Service regarding GTW Railroad Fleet. One unit, L.H. ball joint dropped out and a check of their 90 truck fleet revealed 22 cracked L.H. lower control arms. Dave Hazelhurst working with GTW to correct the condition.

10-14-87 Received 1 L.H. lower control arm and letter from Gary Haviland. See attachments # 12 & 12A

10-15-87 Received phone call from Doug Sloan Truck & Bus Legal Group 8-353-5106 regarding cracking lower control arms and gave him information over the phone relative to dates when SKD started supplying and when correction was in place. See 7-26-84 & 7-18-86

11:15am

10-16-87 Met with Charles R. Matthews from Product Investigation, GM Tech Center to review some of the information attached in this report and in his report.

1:00pm

000-128

10-21-87

Dexed Lab Report 6-39. Attachment # 6D to C.R. Matthews
8-226-7998 Dex # 8-226-8018

10-29-87

Met with Emil Macionski Truck & Bus Rel. Group regarding
cracked lower control arms and was requested to provide an
update to PPEC.

Any additional questions please contact D.H. Pokriefka, GM Network 8-564-2534.

Sincerely,

D.H. Pokriefka

D.H. Pokriefka
Chief Inspector Plant # 56

cc: Mr. E. J. Baker Jr.
J. J. Bentley
R. Gardstrum
S. Jones
E. Macionski
R. Potts
J. M. Richards
A. L. Snoddy
J. Stearn

000179

INSPECTION SAMPLE APPROVAL REPORT

Model

Date of Issuance: 4-23-84
 Checked to S/P Dated: 7-17-73
 Samples from Lot Number: Sample
 Date Received: 4-23-84
 Supplier: S.E.D. Mfg. Co.

Part Number: 6263891 & 92
 Part Name: Arm-Steering Knuckle L/C/A
 Quantity: 2 pcs
 Pattern(s) Number: _____

INSPECTION RESULTS

Dimensional Conformance Check: ☐ Dimensionally OK ☒ See attached sheet(s)

Chevrolet Laboratories Laboratory
 Lab Lot Number: 1008 - 1010 Steel Analysis: ☐ Accept ☐ Reject ☐ Passable

Comments: _____

Laboratory Inspector: Kenneth H. BrownDate: 4-28-84**DISPOSITION**

Based on the results above, your samples have been:

☐ Approved☒ Provisionally approved☐ Correct and proceed with shipments; corrections must be made on the first production shipment.☐ Proceed with _____ pieces in production shipments and submit new samples.☐ Accept as received. Proceed with shipments; however, samples for new dies or molds must reflect corrections to dimensional discrepancies.☐ REJECT - SUBMIT NEW SAMPLES.Supplier verbally contacted: Jerry Zelle - office by: George De Ville Date: 5-7-84

Comments: _____

Disposition authorized by: D. A. SeliskiDate: 5-4-84

Superintendent of Inspection

Date: _____

000180

INSPECTION SAMPLE APPROVAL REPORT

Model

Date of Issuance: 5-22-84
 Checked to B/P Dated: 7-17-73
 Samples from Lot Number: Sample
 Date Received: 5-18-84
 Supplier: S.K.D. Mfg.

Part Number: 6263892
 Part Name: Arm - Steering Knuckle
 Quantity: 1 pc.
 Pattern(s) Number: _____

INSPECTION RESULTS

Dimensional Conformance Check: ☒ Dimensionally OK ☐ See attached sheet(s)

Chevrolet Laboratories Laboratory
 Lab Lot Number: 1008 - 1010 Analysis: ☐ Accept ☐ Reject ☐ Passable

Comments: _____

Labut Inspector: Kenneth Hammons Date: 5-22-84

DISPOSITION

Based on the results above, your samples have been:

☒ Approved Note: Item #4 to be corrected by source, per J. Zelle at SKD on 5-24-84.

☐ Provisionally approved

☐ Correct and proceed with shipments; corrections must be made on the first production shipment.

☐ Proceed with _____ pieces in production shipments and submit new samples.

☐ Accept as received. Proceed with shipments; however, samples for new dies or molds must reflect corrections to dimensional discrepancies.

☐ REJECT - SUBMIT NEW SAMPLES.

Supplier verbally contacted: J. Zelle by: D. A. Selenski Date: 5-24-84

Comments: _____

Disposition authorized by: D. A. Selenski Date: 5-24-84

Superintendent of Inspection

000/181

JUL 05 1984

Truck & Bus Group
General Motors Corporation
31 Judson Street
Pontiac, Michigan 48056

Truck & Bus Group

cc
T. CASEY
D. PORRIS
R. TURNETT
FYI

June 27, 1984


Mr. R. M. Brown Jr.
Detroit Gear and Axle
1840 Holbrook Avenue
Detroit, MI 48212

Subject: Validation Testing Update

Lower control arms 6263891-2 are approved for use in arm asms 14005167-8.

You will be updated regarding the balance of the test program as significant portions are completed.

Very truly yours,


D. C. Raber
Truck Chassis Components

DCR/kaj

cc: M. B. Madden
R. Stach
H. L. Western
R. D. Wood

243 715

000182

INSPECTION SAMPLE APPROVAL REPORT

Model

Date of Issuance: 8-7-84
 Checked to B/P Dated: 7-17-73
 Samples from Lot Number: Sample
 Date Received: 7-18-84
 Supplier: K. S. D. Mfg.

Part Number: 6263091
 Part Name: Arm-Steering Buckle 1/C/A
 Quantity: 1 pc.
 Pattern(s) Number: _____

INSPECTION RESULTS

Dimensional Conformance Check: ☐ Dimensionally OK ☒ See attached sheet(s)

Chevrolet Laboratories Laboratory
 Lab Lot Number: 1008 - 1009 Analysis: ☐ Accept ☐ Reject ☐ Passable

Comments: _____
 Inspector: Kenneth Hammons Date: 8-7-84

DISPOSITION

Based on the results above, your samples have been:

- ☒ Approved Item #4 to be corrected by source per J. Zelle at S.K.D. on 8-8-84.
 (Corrected sample to be submitted)
- ☐ Provisionally approved
- ☐ Correct and proceed with shipments; corrections must be made on the first production shipment.
- ☐ Proceed with _____ pieces in production shipments and submit new samples.
- ☐ Accept as received. Proceed with shipments; however, samples for new dies or molds must reflect corrections to dimensional discrepancies.
- ☐ REJECT - SUBMIT NEW SAMPLES.

Supplier verbally contacted: Jerry Zelle by: Kenneth Hammons Date: 8-8-84
 Comments: _____

Disposition authorized by: George De Ville Date: 8-8-84

Superintendent of Inspection

Date: _____

000483

Customer
TO INVESTIGATION031230-999
031230-1071 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17
1 G B H P 3 2 J 4 P 3 3 0 8 9 2 4

Veh. Line Body Type Eng. Tr. Pl.

30062

Odometer

Car Report

Truck Report

Part # 14026581

Parts Returned

Material Disposition

Plate

Select Material List Item

Name CONTROL ARM

Yes
No
Held

Yes

Product Assurance

Other

A.T. Higgins

Yes No

Organization-Location

Personnel Contacted-Source of Information

FINK BAKERY - LONG ISLAND CITY, N.Y.

FSR 0301 JAD

MIKE JANIZZI

Engine

Trans.

Axle

Other 626 Datsun, Three 70's, H.D. Super
C.M. AIR BASE IN ABOUT D/N 367262, 0,000

Report Subject

FS, P3 FR SUSP. LOWER CONTROL ARM, BALL JOINT DISASSEMBLED, REPAIR ARM

Owner's Complaint

Fleet operates 60-70 1983-85 P30 VANS used to deliver bread goods in
 the New York area. Find of seven 1985 vehicles in southern New York
 Operation Broken Left about lower control arms. None of the 1983-84 vehicles had
 experienced the problem. The vehicles with the problem control arms are
 What Was Found Operated from Long Island City - New York City, which has poor roads but
 these 3 vehicles have all been used to deliver bread to suburban areas
 on Long Island and in Connecticut.

All 3 lower control arms broke at the outside front edge and the
 cracks opened to allow the lower ball joint to disengage from the
 control arm.

ILLEGIBLE

Fleet personnel have been advised to inspect the entire 1985 fleet for cause.
 They will return any additional cracked control arms found.

Additional Vehicles with Broken Control Arms

V.I.N. 1GBHP32J5F3320974, 44465 miles

TOUCH 7580

V.I.N. 1GBHP32J3P3320376, 52005 miles

TOUCH 7580

Source Bumper & Bracket missing from this vehicle's control arm. Fleet personnel
 say vehicle was towed in with bracket missing. When towed in

Mail To:
 Technical Service Operations
 C.C.O. Room 183-138
 30007 Van Dyke Warren, Michigan 48090

Page 1

1

9.2. WATSON

F. 100184

CHEVROLET

Chevrolet Motor Division
General Motors Corporation

Customer

031230-999

Component

031230-158

NATIONAL SERVICE
TO OPERATIONS NOTED

☐ J. SMITH
☐ R. POOLE
☐ J. WICKLE
☒ J. B. GITTIN
☐ J. HARVEY
☐ D. DEDERON

Field Product Report

0236JRW

Personal Investigation

Yes ☒No ☐

Contact Date 021886

Special Investigation/Assignment No

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17
1 G C G C 2 6 J 3 F F 1 4 0 3 0 8

Veh. Line Body Type Eng. Tr. PK.

94535

Odometer

Car Report

Truck Report

Part # 14026581

Parts Returned

Yes ☐
No ☒

YES

Material Disposition

Plant ☐

Product Assurance

Other ☒

GMC

Select Material 1st It?

Yes ☐

Organization-Location

CONNECTICUT LIMOUSINE SERVICE - MILFORD, CONN.

Personnel Contacted-Source of Information
F.S.P.R. 0201 MWV
MOC - FORMER ST BLOOT

Engine

Trans.

Axle

Other

Report Subject

N/A 1G C 2 C 2653 F 732856

85, C2, FR SUSP, Lower control arm, Ball joint disengaged, cracked

Owner's Complaint

BALL JOINTS HAVE DISENGAGED FROM THE LEFT LOWER CONTROL ARM ON 2 VEHIC

Operation

CONNECTICUT LIMOUSINE SERVICE OPERATES 200 SUBVANS WHICH ARE USED TO

TRANSPORT PASSENGERS TO AND FROM METROPOLITAN NEW YORK AIRPORTS. THE VEHICLES

HAVE BEEN STRENGTHEN BY RETROFITTING TO WHEEL BASE AN ADDITIONAL 6.5" CONVER

SIGN IS DONE BY THE ARMSTRONG CONVERSION CO. VEHICLES CARRY UP TO 11

PASSENGERS AND LUGGAGE. THE FLEET'S ENGINEERING DIRECTOR BELIEVES VEHICLE

OVERRIDE 27 TIMES AT MAXIMUM OR SLIGHTLY ABOVE THE RATED GVW THE COLUMBIA

CO HAS GVW STICKERS ON VEHICLES PRIOR TO 1985 SHOWING A GVW OF 8600 LBS

4200 FRONT AND 4200 REAR. THE 1985 VEHICLES SHOW ONLY THE FACTORY GVW R

ATING PLATE GVW IS 8600, GVW FRONT IS 3800, GVW REAR IS 6,000.

BALL JOINTS DISENGAGED FROM THE CONTROL ARMS AND SUBSEQUENT INSPECTION OF

VEHICLES THE CONTROL ARMS WERE CRACKED AROUND THE BALL JOINT HOLE. THE FLEET

INSPECTED ALL OF THEIR 48 1985 MODELS IN SERVICE AND FOUND CRACKED LOWER

CONTROL ARMS ON 12 VEHICLES ALL CRACKS HAVE BEEN ON THE 1st LOWER CONTROL

Results ARM. THE CRACK STARTS AT THE LOWER OUTBOARD EDGE AND TRAVELS ACROSS

AND AROUND THE BALL JOINT HOLE.

THE FLEET HAS REPLACED ALL OF THE CRACKED CONTROL ARM PARTS AND IS BEING

HOLD FOR RETURN IF REQUESTED TO WRITE'S RETURNING ONE ARM FOR

Signature

Mail To:
 Technical Service Operations
 G.C.O. Room 183-138
 30007 Van Dyke Warren, Michlen 48090

Page 1 of 2

J.R. W. W. W. W.
 Jay Lewis 396-3997

50055-5

ASD

Field Product
Report

1

CHEVROLET MOTOR DIVISION
General Motors Corporation

Customer

1851-250-9149

Component


NEE-250-1158

02365RW


INSPECTION

The company has operated stretched Suburbans since 1979 and averages about 300,000 miles in service. Previously this problem has never been observed.

TOP VIEW
OF
CONTROL
ARM



CRACK



SIDE VIEW OF
CONTROL ARM

CRACK STARTS HERE AT FLANGE
EDGE.

IN ADDITION TO THE VEHICLE LISTED ABOVE THE FOLLOWING VEHICLES HAD

CRACKED CONTROL ARMS.

V.I.N.

MILEAGE

1GCCG26T5FF136521

105,238

JXFF138376

100,039

J5FF136809

102,388

J2FF143636

97,630

J8FF137663

88,501

J1FF138699

92,323

J3FF144345

92,411

J5FF145181

77,037

J1FF136158

92,403

J6FF167091

73,348

W6FF130867

104,000

J6FF139458

73,348

WITH EXCEPTION OF ONE VEHICLE WITH A 74L ENGINE THE REMAINING VEHICLES ARE EQUIPPED AS FOLLOWS. B3J Diesel, C69 A/C, R52 R.D. STEERING, G74 J23 AXLE, MX1 TRANS, H82 FUEL TANK, V02 COOLER, Z62 SCOTSDALE, 129"WB, LT 235/85R160 AND 16F Tires, 624 Diesel

O.R. WATSON

K.E.S.

Mail To: Product Assurance - Field Activities

C.C.O.B. Room 183-156

39007 Van Dyke Warren, Michigan 48090

Signature

Total 185

GSD 167-A
Rev 11/67



GENERAL MOTORS DE MEXICO, S.A. DE C.V.

5
PLANTA MEXICO
AV. EJERCITO NACIONAL 843
APARTADO 107 BIS
MEXICO 1, D.F.

June 5, 1986.

Mr. William Scribner
Quality Control Manager
Saginaw Steering Gear
Axle Div.

Attached you will find the results on 3 sample layouts performed in our Quality Control Department, Mexico City Plant.

Needless to say, why we are concern about the problems we have out in the field.

I know we can count on you to help us to solve this discrepancies, but we need material with zero discrepancies, therefore, we are going to be waiting for your answer as soon as possible.

Regards,

Mario V. Nájera
Quality Control Dept.

000187

**Saginaw**

Inter-Organizational

Subject: FLEET SERVICE PRODUCT REPORT 0325JRW

Corrected letter

Date: 11-2-87

From: D.H. Pokriefka

To: R.H. Meinhardt

FINK BAKERY

3/4 Ton Lower Control Arm

#1 Left Hand

CROSS SHAFT BUSIHING TORQUE: 300 Ft Lbs
250 Ft Lbs
Spec 125 min.

SHAFT MOVEMENT: Free
JOUNCE BUMPER: Missing

Brackets: Shock Bracket-OK
Jounce Bracket - repaired hand weld and heavy crash thru
witness marks.

BUSHINGS: Seated
BALL STUD: Present "0" pushout load.

TEARDOWN INSPECTION: Arm stamping is cracked from outer wall end face
to the ball stud mounting hole. Stamping source
is SKD (SEE LAB REPORT #6-39)

3/4 Ton Lower Control Arm
#2 Left Hand

CROSS SHAFT BUSHING TORQUE: 200 Ft Lbs
150 Ft Lbs
Spec 125 min

SHAFT MOVEMENT: Free
JOUNCE BUMPER: Missing
BRACKETS: Shock Bracket - OK
Jounce Bracket - missing welds - did pull metal
BUSHINGS: Seated
BALL STUD: Missing
TEARDOWN INSPECTION: Same as # 1

00018R

FLEET SERVICE PRODUCT REPORT 0325JRW
July 9, 1986 continued

3/4 Ton Lower Control Arm
3 Left Hand

CROSS SHAFT BUSHING TORQUE 250 Ft Lbs
 200 Ft Lbs
 Spec 125 min.

SHAFT MOVEMENT: Free

JOUNCE BUMPER: Compressed

BRACKETS: Shock Brkt - OK

BUSHING: Seated

BALL STUD: Present "O" pushout load

TEARDOWN INSPECTION: Same as # 1

SUMMARY: The lower control arm stamping from SKD Company appears to have a small radius at the transition of the side wall to the ball stud nose. Current stampings also have a small radius in the same area. SKD has changed the trim to increase the radius to 1 inch and provide additional strength in the ball stud area (See Sample)

In addition the customer may be using the front suspensions at max or beyond max load range which is evidenced by broken welds and compressed jounce bumpers. Suggest a heavier rated front suspension be used (14032908 H-22) that has reinforcements at all critical points.

Correction: Additional inspection and dimensional checks have revealed that the stampings are from SKD. D.H.P. 11-2-87

D. H. Pokriefka

D. H. Pokriefka
Chief Inspector, Plant # 56

000100



Saginaw

Inter-Organizational

Subject: FLEET SERVICE PRODUCT REPORT 0236JRN

Corrected Letter

Date: 11-2-87

From: D.H. Pokriefka

To: R.H. Meinhardt

Connecticut Limousine Service
3/4 Ton Lower Control Arm
#1 Left Hand

CROSS SHAFT BUSHING TORQUE: 250 Ft Lbs
200 Ft Lbs
Spec 125 min.

SHAFT MOVEMENT: Free

JOUNCE BUMPER: Compressed

BRACKETS: Shock Bracket - OK
Jounce Bracket - 1 weld broken

BUSHINGS: Seated

BALL STUD: Missing

TEARDOWN INSPECTION: Arm stamping cracked from the outer wall end face
to the ball stud mounting hole. Stamping source is
SKD. See Lab Report #6-39

3/4 Ton Lower Control Arm
#2 Left Hand

CROSS SHAFT BUSHING TORQUE: 90 Ft Lbs
100 Ft Lbs
Spec 125 min.

SHAFT MOVEMENT: Free

BRACKETS: Shock Brkt - OK
Jounce Bumper - Compressed
Jounce Brkt - OK

BUSHING: Seated

BALL STUD: Missing

TEARDOWN INSPECTION: Same As # 1

SUMMARY: The lower control arm stamping from SKD Company appears

000190

to have a small radius at the transition of the side wall to the ball stud nose. Current stampings also have a small radius in the same area. SKD has changed the trim to increase the radius to 1 inch and provide additional strength in the ball stud area. (See Sample)

In addition the customer may be using the front suspensions at max or beyond max load range, which is evidenced by broken welds and compressed jounce bumpers. Suggest a heavier rated front suspension be used (14032908 H-22) that has reinforcements at all critical points.

Correction: Additional inspection and dimensional checks have revealed that the stampings are from SKD. DHP 11-2-87

D. H. Pokriefka

D. H. Pokriefka
Chief Inspector, Plant # 56

000191

METALLURGICAL LABORATORY

LAB NO. 6-59
 PART NAME Sleeper Knuckle
 FROM PLANT #56 PART NO. 1213991
 SOURCE SKD Company SPECIFICATION SAE 1008 or 1010
SAE 1008 or 1010

HISTORY OF MATERIAL Reliability Test
Part cracked at be
stud mounting hole at draw out

OBJECT OF INVESTIGATION Failure

CONCLUSION The crack appears to be fatigue in origin initiated at
the outer wall end face of the drill stud mounting hole.
Fracture is fine grained and smooth. It is also present and fine
along the contour of the part for a distance of approximately 2.0.
The part has a hardness of R/R 65-66 and has a fine ferrite
structure with no inclusions at the fracture. The

CHEMICAL
 ANALYSIS
 5-20

PHYSICAL

MICRO

5-10-50
 385

MACRO

OTHER


ILLEGIBLE

SIGNATURE DR
 TITLE LAB. INSP.

Visual Examination

The crack passes through the outer wall thickness and extends for a length of approximately 20'. The fracture faces are fine grained and smoother at the drawn edge end face and progressed along the contour of the part with a slightly coarse striated appearance. See 51 macrograph below.

ILLEGIBLE



11

FRACTURE AT BALL STUD MOUNTING HOLE

AS RECEIVED

LABORATORY REPORT

Sample No.	Q# Ident. #:	4-1726	6-39
	Mat'l. Ident.	SAE 9504X	SAE 1008-1010
	Part Name:	Lever	Lower Control Arm
	P/N:	15595104	6263891
	Source:	Van Wormer	

C	0.0005	0.008%	0.0005
S	0.0005	0.005%	0.0005
P	0.0005	< 0.005%	0.0005
SI	0.0005	< 0.01%	0.0005
HM	0.0005	0.32%	0.0005
QT	0.0005	< 0.01%	0.0005
NI	0.0005	< 0.01%	0.0005
NO	0.0005	< 0.01%	0.0005
V	0.0005	< 0.005%	0.0005
Al	0.0005	0.065%	0.0005
Co	0.0005	0.02%	0.0005
Ti	0.0005	< 0.005%	0.0005
Fe	0.0005	< 0.005%	0.0005
CS	0.0005	< 0.005%	0.0005
Ta	0.0005	0.027%	0.0005
V	0.0005	< 0.01%	0.0005

~~Sample 4-1726 & 4-1730 check like SAE 9504X.~~

Sample 6-39 checks like SAE 1008 or 1010.

ILLEGIBLE

We certify the above analysis to be the true result obtained on the described sample(s).

Analytical Associates, Inc.

by _____

Charles K. Peak

Information and data in this report is correct and reliable to the best of our knowledge. No part of this report is to be reproduced for any purpose without our written consent.

Results are not guaranteed and no responsibility is assumed.

Sworn and subscribed before me a Notary Public in and for Wayne

County, State of Michigan this _____ day of _____

19____

Commission Expires _____

Duplicate Lab Report

000194

Physical Properties

- R/R Core Hardness
(Adjacent to crack)

65-66

Metallography (Radial section, including crack)

The structure consists of fine grained ferrite (size 6-8 μ) and filament carbide located primarily in the grain boundaries. There is secondary α in the grain which is inter and trans grain with no apparent α in the general structure or at the origin. There is no evidence of a rim or non-metallic inclusions.

Spec. Low Carbon Steel

ILLEGIBLE

ASTM Grain Size in μ \times 100

000195

T.I.R. No. T-87G-03A-00LT
T.W.O. No. 27G02-009
Page 2 of 2

7A

GC7812/86340

197101



Customer

URS CODE - [] [] [] []

Component

URS CODE - [] [] [] []

R.S.E. Coding Use Only

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17

1 G C G 2 2 1 5 7 1 5 1 1 1 1 1 1 1 1 1 1 0 8

CO USE ONLY

Origin/Type Veh. Line Body Type Eng. Tr. Pl. Production Sequence Number

1116000

Car Report

Truck Report

Part # 1426581

Material Used For RSE

RSE Material Disposition

Plant

Name Control arm

Yes ☒ No ☐

Product Assurance

Other

Organization—Location

Personnel Contacted—Source

Engine

Trans.

Axle

Other

Report Subject

Control arm cracks (left side only) if not noticed ball stud pulls out & control arm ~~pulls~~ drops on road

Owner's Complaint

Operation

Note - left and right control arms replaced and sent to service operation for E. Albers rep. int. Typical ~~new~~ crack is beginning for left arm. Right arm is clear

What Was Found

The account questions why the condition did not occur in the model years 1979, 1980, 1981, 1982, 1983 and 1984 with the typical vehicle returns in service for 300,000

What Was Done

On 1985 model year after ignition failures with mileage as low as 20,000 at the time of failure account reflected all left lower control arms on the fleet on 1985 models. No repeat failures have been experienced - no failures have been found on the right arm.

To date 14 failures have occurred on 1986 models

RSE Comments/Action

Signature

J. Albers

F 000198

E ONLY

ILLEGIBLE

Signature

Central Service

RSE

1 - FMSO

5 - Attach to Material

2 - CO. Svcs Operations

4 - Fleet Service Manager



Saginaw

Inter-Organizational

Subject: Test Information Report
T-876-03P-002LT

Date: 3-31-87

From: Mr. D. H. Pokriefka

To: Mr. E. L. Sturm

GM Truck Group
Milford Proving Ground
Vehicle # 2GCHG31KSH410005
Mileage: 8755

L.H. Lower Control Arm
Part # 14066885

Cross Shaft Bushing Torque:	240 Ft. Lbs. 210 Ft. Lbs. B/P Spec 125 Min.
Shaft Movement:	Free
Jounce Bumper:	Missing
Shock Brkt & Reinforcement Welds:	OK
Jounce Bumper Brkt Welds	See attached Lab Report 6-44 and 6-43
Ball Stud:	Push out load "0" B/P Spec 2000 # Min.
Lower Control Arm Stamping:	50 MM crack at rear of ball stud
Summary:	See Lab Reports 6-43 & 6-44

The lower control arm stamping from SKD appears to have a small radius at the side wall to the ball stud nose. SKD has changed the trim to increase the radius to one inch and provide additional strength in the ball stud area.

The front suspension may be loaded at maximum or beyond maximum load range which is evidenced by broken welds and compressed jounce bumpers.

D. H. Pokriefka
D. H. Pokriefka
Chief Inspector

cc: R. M. Brown



Saginaw

Subject: Fleet Service Product Report HWD1103

3-31-67

From: Mr. D. H. Pokriefka

Mr. E. Albers

Vehicle # 1GCGC26J56P109708
Mileage 116,000
14026581
3/4 Ton Lower Control Arm

Cross Shaft Bushing Torque:	210 Ft. Lbs. 200 Ft. Lbs. Spec. 125 Ft. Lbs Min.
Shaft Movement:	Free
Jounce Bumper:	OK
Shock Brkt & Reinforcement Welds:	OK
Jounce Bumper Brkt. Welds:	OK
Ball Stud:	Seated Push out B/P Spec 2000 # Min. Push out 3800 # and still seated.
Lower Control Arm Stamping:	Small indication of a crack left
Date: SKD 23 5	side of ball stud hole.

14026582
3/4 Ton Lower Control Arm

Cross Shaft Bushing Torque:	250 Ft. Lbs. 200 Ft. Lbs. Spec. 125 Ft. Lbs. Min.
Shaft Movement:	Free
Jounce Bumper	OK
Shock Brkt & Reinforcement Welds:	OK

000200